


CAUTION: DISCONNECT ELECTRIC CURRENT BEFORE SERVICING

C C A M	TERM.	CIRCUIT	REGULAR				PERM. PRESS				DELICATE				OFF
			WASH (16 MIN)	PUMP (6 MIN)	RINSE (4 MIN)	PUMP (10 MIN)	WASH (12 MIN)	PUMP (6 MIN)	RINSE (4 MIN)	PUMP (6 MIN)	WASH (8 MIN)	PUMP (6 MIN)	RINSE (4 MIN)	PUMP (6 MIN)	
0	2	COLD WATER	HOT	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF
2	2	HOT WATER	WARM	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF
4	8	LID SW BYPASS	WARM	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF
6	11	SPIN DIR	WARM	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF
8	14	AGITATE DIR	WARM	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF
10	17	SPIN DIR	WARM	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF
12	8	MOTOR CONTROL	WARM	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF
14	8	P.S. BYPASS	WARM	COLD	P	SPIN	P	P	SPIN	P	P	P	SPIN	P	OFF



WIRING DIAGRAM
P/N 13407800